



**Vertical Member Requiring Repair at  
South Side of Rail Bridge Mid-span  
(Close Up)**